

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

318
East
1/4-1/2
0.488 mi.
2575 ft.

MAN HOLE #1501
NEPTUNE AV &W 2ND ST
BROOKLYN, NY

NY Spills S103938724
N/A

Relative:
Higher

Actual:
7 ft.

SPILLS:

Name: MAN HOLE #1501
Address: NEPTUNE AV &W 2ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9903357 / 1999-07-26
Facility ID: 9903357
Facility Type: ER
DER Facility ID: 230074
Site ID: 283656
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1999-06-23
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1999-06-23
CID: 257
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-06-23
Spill Record Last Update: 2002-04-15
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: RICHARD ROACH
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL con ed e2mis notes: Found 3 oz of dielectric oil on 50 gal of water leaked from cable end seems to be contained. 1 liquid sample was taken. <1ppm, cleanup completed at 1650 hrs. Update - No leaking company equipment."

Remarks: "3oz's in 50gal's water from a cable ref #125720 - cleanup pending test results"

All Materials:

Site ID: 283656
Operable Unit ID: 1077950
Operable Unit: 01
Material ID: 303282
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Oxygenate:

Not reported